



Technical Service Bulletin

Reference:

TSB10-130-009

Date:

Sept 2010

APPLIED VEHICLE: 2007 – 2008 GM C/K truck Low or Spongy Pedal after routine brake service

SERVICE INFORMATION:

Some vehicles may exhibit a low or spongy pedal after wheel end brake service that cannot be remedied by bleeding the brakes. This may be due to a prematurely deteriorated seal in the master cylinder. Remove snap ring and rearmost piston from master cylinder to inspect seals. If any deformation or deterioration of seals is present, replace the master cylinder.

